



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

## Inspection Report Minerals Regulatory Program August 10, 2010

Reviewed: PPB

<b>Mine Name:</b> Thomas Pit	<b>Permit Number:</b> M/011/0002
<b>Operator Name:</b> Lakeview Rock Products, Inc.	<b>Inspection Date:</b> April 22, 2010
<b>Inspector(s):</b> L Heppler	<b>Time:</b> 10:00 am
<b>Other Participants:</b> John Burggraf	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Renewal Date:** 04-01-2011 **Bond Amount:** \$142,000

**Purpose of Inspection:** Routine annual Inspection. This site was inspected as a large mine site on 10/18/2007

**Inspection Summary:** Drainage was noted through out the mine site, due to weather, but all drainage was internal to the permit. Photos were taken to document site conditions.

**Conclusions and Recommendations:** It is the recommendation of the Division to grade the floors of the pit to drain to sump sites internal to the mine permit. It is also the recommendation of the Division that the operator interm seed areas that are disturbed, but not fully reclaimed. Interm seeding helps with dust suppression and reduces the chance for weeds to establish in disturbed areas. OGM to continue annual inspections and monitor the site when in the area.

**Inspector's Signature**

LAH:vs

cc: Scott Hughes – Lakeview Rock Products

O:\M011-Davis\M0110002-ThomasPit\Inspections\Insp-04222010.doc








View from above to pit floor



View from above to pit floor



Upper and lower highwalls



Fuel storage area